PATENT

Attorney Docket No. 4329.3210

FEB 2 0 2008

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

re U.S. Patent No.: 7,327,013 B2

Inventors: TAKESHI SHIBATA ET AL.

Issue Date.: February 5, 2008

For: STENCIL MASK WITH CHARGE-UP

PREVENTION AND METHOD OF

MANUFACTURING THE SAME

Certificate
FEB 2 2 2008
of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. § 254, and 37 C.F.R. § 1.322, this is a request for a Certificate of Correction in the above-identified patent. The mistakes identified in the appended Form occurred through the fault of the Patent Office, as clearly disclosed by the records of the application which matured into this patent.

Two (2) copies of PTO Form 1050 are appended. The complete Certificate of Correction involves one (1) page. Issuance of the Certificate of Correction containing the correction is earnestly requested.

Please charge any required fees not included herewith to Deposit Account 606-0916.

Respectfully submitted,

GARRETT & DUNNER LEP

FEB 2 2 2008

Dated: 2 20 08

Richard V Burgujian

Reg. No. 31,744 (202) 408-4000

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,327,013 B2

Page 1 of 1

APPLICATION NO.:

10/743,522

ISSUE DATE:

February 5, 2008

INVENTORS:

Shibata et al.

It is hereby certified that an error or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page, item (57), delete the ABSTRACT in its entirety and substitute therefor:

-- In a stencil mask, a conductive thin film has first openings in it. An insulating film is formed in the region of the conductive thin film excluding the first openings. A conductive support is formed on the insulating film. A second opening goes through the conductive support and insulating film and reaches the surface of the conductive thin film. A conducting member is formed in the second opening. The conducting member connects the conductive support and conductive thin film electrically.--

Claim 20, column 14, line 3, change "region the" to --region, the--.

RECEIVED-USPTO

FEB 2 2 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,327,013 B2

Page 1 of 1

APPLICATION NO.:

10/743,522

ISSUE DATE:

February 5, 2008

INVENTORS:

Shibata et al.

It is hereby certified that an error or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page, item (57), delete the ABSTRACT in its entirety and substitute therefor:

-- In a stencil mask, a conductive thin film has first openings in it. An insulating film is formed in the region of the conductive thin film excluding the first openings. A conductive support is formed on the insulating film. A second opening goes through the conductive support and insulating film and reaches the surface of the conductive thin film. A conducting member is formed in the second opening. The conducting member connects the conductive support and conductive thin film electrically.--

Claim 20, column 14, line 3, change "region the" to --region, the--.

nedical publication